

**CANADA AIR PILOT**

Effective 0901Z 30 SEPTEMBER 2004 to 0901Z 25 NOVEMBER 2004




**NOT FOR NAVIGATION**

SID(VECTOR)

**HALIFAX THREE DEP (CYHZ 3)**

HALIFAX INTL  
HALIFAX NOVA SCOTIA



© 2004 Her Majesty The Queen in Right of Canada, Department of Natural Resources

Source of Canadian Civil Aeronautical Data: © 2004 NAV CANADA

**DEPARTURE ROUTE DESCRIPTION**

- ALL RUNWAYS:**
1. Climb runway heading or as assigned for radar vectors.
  2. Maintain 5000 ASL or as assigned.

COMMUNICATION FAILURE - TRANSPONDER MODE A/3 CODE 7600

On recognition of communication failure 10 minutes or less after take-off and in IFR weather conditions proceed as follows:

1. Upon reaching last assigned altitude proceed directly on course;
2. Maintain last assigned altitude for 10 minutes after take-off; then
3. Climb to flight planned altitude.

Note: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedure for communication failure enroute.

**HALIFAX THREE DEP (CYHZ 3)**

EFF 19 FEB 04 CHANGE: 2003 Mag Var

HALIFAX NOVA SCOTIA  
HALIFAX INTL  
NAD83

**NOT FOR NAVIGATION**